SOUTHERN MAPPING AND ENGINEERING COMPANY

4521 W. MARKET ST.



TELEPHOTE SECTIVE

GREENSBORO, NORTH CAROLINA 27407

April 7, 1993

Ms. Kelly Gage Guilford County Emergency Services 1002 Meadowood Road Greensboro, North Carolina 27409

RE: UST Closure Assessments at Piedmont Triad International

Airport

Dear Ms. Gage:

Enclosed herewith are the certificates, letters and other information requested in your memorandum of March 23, 1993 to Lisa Elmore at Piedmont Triad International Airport.

I have contacted Thad Chesson of Piedmont Environmental Services, Inc. and he is going to forward to you the information concerning how the samples were collected and preserved, and how the tools used were decontaminated.

The sampling results from the monitoring wells installed by Trigon Engineering will be forwarded by Lisa Elmore or Trigon Engineering.

If there are any questions concerning this, or if additional information is needed, please contact me at (919) 294-4441.

Sincerely,

SOUTHERN MAPPING & ENGINEERING COMPANY

Chrispen J. Colenda

CJC/pg

Enclosures:

cc: Lisa Elmore



P. O. Box \$266 x 1 8 6 3 1. Greensboro, NC 27419 (919) 668-4821

November 29, 1990

Tom Salley
NC Dept. of Environment, Health, and Natural Resources
8025 North Point Blvd. Suite 100
Winston-Salem, NC 27106

Re: UST removal Piedmont Triad Airport Authority Guilford County

Dear Mr. Salley;

Piedmont Environmental Services was contracted to remove eight UST's and one hydraulic lift by the Piedmont Triad Airport Authority. We performed this work through Southern Mapping and Engineering Company.

The tanks were pumped and purged of oxygen using dry ice before their removal. Five 3000 gallon gas tanks, one 550 gallon fuel oil tank, one 550 gallon kerosene tank, one 550 gallon waste oil tank, and one hydraulic lift were removed. Soil samples were taken under the excavated tanks as required and the results of those samples are attached. A site map is also attached.

According to the Guilford Laboratories report all the samples tested below the regulatory level except sample 4948 which was taken below the waste oil tank. Based on my phone conversation with you on November 27, we have taken another sample in this hole. This sample is now at Guilford Laboratories to run a RCRA metals and a PCB test. We will submit this report to you as soon as we get it back from the lab.

We have backfilled all the holes except the waste oil pit and we plan to close it soon. If we can help you with any other information please let me know.

Thad Chesson

Sincerely,

10

cc: Terry Cole, Guilford County Public Health Chrispen Colenda, Southern Mapping and Engineering Co.



GUILFORD COUNTY DEPARTMENT OF PUBLIC HEALTH DIVISION OF ENVIRONMENTAL HEALTH

301 N. Eugene Street P.O. Box 3508 Greensboro: NC 27401 Phone: (919) 373-3771

 \mathbb{R}^{C}

UNDERGROUND TANK REMOVED OR ABANDONED IN PLACE

TO BE TYPED OR PRINTED-

Owner's Name: Piedmont Triad Airport Authority
Address: PO Box 35005 Greensboro, NC 27425
Telephone: (919) 665-5600
Property Address: Abondoned Gulf Service Station US 421 at ramp to Regiona)
(if different from above)
Date removal or abandonment: November 12 and 13, 1990
Contractor's Name: Piedmont Environmental Services
Address: PO Box 18631 Greensboro, NC 27419
Telephone: (919) 668-4821
Final disposition of removed product: Piedmont Environmental Services
Evidence of leakage? Yes No
Soil samples taken? Yes X No 1 If yes, results must be forwarded to Health Department
Material used to fill tank: na
(5) 3000 gallons Tank size:gallons (\pm 3) 550 gallons
Final disposition of tank, if removed: Safeway Tank Disposal
Final disposition of contaminated soil, if removed:
Remarks:
·
Hel Chum
White-Health Dept. Signature
Yellow–Fire Dept. Pink–Owner
Date

REGIONAL

To Keautersvick

0542

TO CARENSBORD

November 16, 1990

REPORT OF ANALYSIS

JOB #:

PEI01113

CUSTOMER: Piedmont Environmental

ATTN: Thad Chesson

P.O.#:

Airport Station

SAMPLE:

4944 GAS TANK E NORTH

4945 GAS TANK E SOUTH

TANK F 550 GAL HEATING OIL

4947 # 4948 TANK G 550 GAL KEROSENE

TANK H 550 GAL WASTE DIL

RESULTS		4944	<u>4945</u>	<u>4956</u>	<u>4947</u>	<u>4948</u>
Total Petroleum Hydrocarbons as Gasoline by Method 5030	(ppm)	<10	<10		denis dans same	
Total Petroleum Hydrocarbons by Method 3550	(ppm)		••• ••• ······························	<10	<10	-
Oil & Grease for Petroleum Hydrocar SW-846 Method 9071	bons (ppm)			The first mad		61



November 16, 1990

REPORT OF ANALYSIS

JOB #:

PED01113

CUSTOMER:

Piedmont Environmental

ATTN: Thad Chesson

P. O. #:

Airport Station

SAMPLE:

4940 GAS TANK C NORTH # 4941 GAS TANK C SOUTH # 4942 GAS TANK D NORTH

4943 GAS TANK D SOUTH

RESULTS

<u>4940</u> <u>4941</u> <u>4942</u> <u>4943</u>

Total Petroleum Hydrocarbons (ppm) as Gasoline by Method 5030

(10

(10

(10

(10

Guilford Laboratories. Inc.

J. A. Rayburn



November 16, 1990

REPORT OF ANALYSIS

JOB #:

PES01113

CUSTOMER: Piedmont Environmental

ATTN: Thad Chesson

P. O. #:

Airport Station

SAMPLE:

4936 GAS TANK A NORTH

4937 GAS TANK A SOUTH

4938 GAS TANK B NORTH

4939 GAS TANK B SOUTH

RESULTS

<u>4936</u> <u>4937</u> <u>4938</u> 4939

Total Petroleum Hydrocarbons (ppm)

(10

as Gasoline by Method 5030

(10

(10

<10

Guilford Laboratories, Inc.

CERTIFICATE OF TANK DISPOSAL

Customer					Date	11/23/90				
Reamont Environmental										
Drew storo, n.c. 2749										
		·		Transported by: Predmont Erry.						
Tank Disposal Number	Size	Weight	Product	Residue Amount		Origin				
3593	3,0000) ລາລ#	لمملا	15 gal.	Old air	port-Iluu	4 421			
3594	3,000	2720	لمط	15	Gra	post-Ihu	h.e.			
3595	3,000	<u>ചി</u> ചം	لمطالع	15	-	,				
3596	3,000	2720	عمالك	15	·					
3598	3,000	3170	Das	15		<u></u> .				
3599	550	450	Jue Sil	3						
3000	550	450	Shapanpic	io 3						
3401	550	450	Os stroly	_3	, , , , , , , , , , , , , , , , , , ,	1	-			
	 -	.,,								
<u> </u>							····			
	· 		Total Residue	84 gal						
I				-		•				

Skas N. Joung